

KENWOOD

SERVICE MANUAL

MONITOR WITH RECEIVER

**DMX4710S, DMX40S, DMX5023S, DMX400S
DMX5710S, DMX50S, DMX6523S, DMX500S**

SERVICE POLICY

No service parts available except accessory.




Bluetooth®

Made for
iPhone


Works with
Apple CarPlay

Android
Auto

DC Cable
E3A-1026-00
E3A-1027-00




Extension Parking Cable
E3A-0344-00




Remover
D1C-0006-00



Trim Plate
B0H-0068-00



GPS Antenna Assy
T9A-0147-00
T9A-0163-00



Microphone
T9B-0092-00



【Service Parts Configuration Table】

	DMX4710S(K)	DMX40S(K)	DMX400S(K)WM	DMX5023S(M)
E3A-1026-00	○	○	○	
E3A-1027-00				○
E3A-0344-00	○	○	○	○
D1C-0006-00	○	○	○	○
B0H-0068-00	○	○	○	○
T9A-0147-00	○	○	○	○
T9A-0163-00				
T9B-0092-00	○	○	○	

	DMX5710S(K)	DMX50S(K)	DMX500S(K)WM	DMX6523S(M)
E3A-1026-00	○	○	○	
E3A-1027-00				○
E3A-0344-00	○	○	○	○
D1C-0006-00	○	○	○	○
B0H-0068-00	○	○	○	○
T9A-0147-00				
T9A-0163-00	○	○	○	○
T9B-0092-00	○	○	○	

【Revision History】

Date	Revision
2024/9/20	Additional model DMX400S (K type WM,AZ)
2024/11/27	・Additional models ・DMX5710S(K) ・DMX50S(K) ・DMX500S(K):Walmart ・DMX6523S(M) ・Additional a part GPS Antenna Assy(T9A-0163-00)

KENWOOD

JVCKENWOOD Corporation
Mobility & Telematics Services